

CE



Digital LUX Meter with Flexible Sensor

930T



Digital LUX Meter

930P



Digital Sound Level Meter

970P

Functions	MAX / MIN, Backlight, Auto Power Off with Disable Feature, Data Hold	MAX / MIN, Backlight, Auto Power Off	MAX / MIN / HOLD, Auto Power Off
Range	0.1 ~ 200,000 lux 0.0 ~ 20,000 fc	0 ~ 200,000 lux 0 ~ 20,000 fc	35dB ~ 130dB (31.5Hz ~ 8 KHz)
Accuracy	± 3% + 30 dgt	± 5% rdg + 10 dgt (< 10.000 lux/fc) ± 10% rdg + 10 dgt (> 10.000 lux/fc)	± 1.5dB (under reference conditions)
Resolution	0.1 lux or 0.1 fc	0.1lux or 0.1fc	0.1dB
Selection	lux / fc	lux / fc	-
Power	1.5V AAA x 2 Batteries	9V Battery	9V Battery
Dimension	157 x 54 x 34mm (approx.)	190 x 56 x 39mm (approx.)	172 x 56 x 39 mm (approx.)
Weight	70gms Including Battery (approx.)	135gms Including Battery (approx.)	144gms Including Battery (approx.)
Accessories	Carrying Case, Inst. Manual, 1.5V AAA x 2 Batteries (installed)	Carrying Case, Inst. Manual, 9V Battery (installed)	Carrying Case, Inst. Manual, 9V Battery (installed)



Air Flow Anemometer

961P



Humidity & Temperature Meter

920P

Air Flow Measuring	
Functions	m / Sec, Ft / min, Knots, Km / h, MPH, CFM, MAX / MIN / HOLD, Auto Power Off
Range	1 ~ 25m/s
Accuracy	± (3% rdg ± 0.2m/s)
Resolution	0.01m/s
Temperature Measuring	
Range	0 ~ 50°C, 32 ~ 122°F
Accuracy	± 2°C / ± 4.0°F
Resolution	0.1°C / 0.1°F
Power	9V Battery
Dimension	202 x 56 x 39mm (approx.)
Weight	155gms Including Battery (approx.)
Accessories	Carrying Case, Inst. Manual, 9V Battery (installed)

Humidity Measuring	
Functions	°C / °F / RH Selection, MAX / MIN, Auto Power Off
Range	0% ~ 100% RH
Accuracy	± 3%RH (25°C, 20 ~ 80% RH) ± 3.5%RH (At Other Ranges)
Resolution	0.01%RH
Temperature Measuring	
Range	- 20°C ~ 80°C / - 4°F ~ 176°F
Accuracy	± 0.5°C / ± 0.9°F (25°C) ± 0.8°C / ± 1.5°F (At Other Ranges)
Resolution	0.01°C / 0.01°F
Power	9V Battery
Dimension	173 x 56 x 39mm (approx.)
Weight	139gms Including Battery (approx.)
Accessories	Carrying Case, Inst. Manual, 9V Battery (installed)